

MODEL G0609X 12" JOINTER w/SPIRAL CUTTERHEAD MANUAL INSERT

The Model G0609X is the same as the Model G0609, except it has a spiral cutterhead. Besides the data sheet and parts in this insert, the content in the Model G0609 owner's manual is the same for both machines. Before operating your new machine, you MUST read and understand this insert and the entire Model G0609 manual to reduce the risk of injury from improper use or setup.

If you have any further questions about this manual insert or the differences between the Model G0609X and the Model G0609, contact our Technical Support at (570) 546-9663 or email <u>techsupport@grizzly.</u> com.



COPYRIGHT © SEPTEMBER, 2007 BY GRIZZLY INDUSTRIAL, INC. REVISED JULY, 2008. (TR) WARNING: NO PORTION OF THIS MANUAL MAY BE REPRODUCED IN ANY SHAPE OR FORM WITHOUT THE WRITTEN APPROVAL OF GRIZZLY INDUSTRIAL, INC.

#TR10028 PRINTED IN CHINA



MACHINE DATA SHEET

Customer Service #: (570) 546-9663 · To Order Call: (800) 523-4777 · Fax #: (800) 438-5901

MODEL G0609X 12" JOINTER W/ SPIRAL CUTTERHEAD

Product Dimensions:	
Weight	
Length/Width/Height	
Foot Print (Length/Width)	
Shipping Dimensions:	
Туре	
Content	
Weight	
Length/Width/Height	88-3/8 x 29-3/4 x 40-1/2 in.
Electrical:	
Switch	Magnetic with Thermal Overload Protection
Switch Voltage	_
Cord Length	
Cord Gauge	
Recommended Breaker SizePlug	•
i lug	
Motors:	
Main	
Туре	TEFC Capacitor Start Induction
Horsepower	3 HP
Voltage	220V
Prewired	
Phase	<u> </u>
Amps	
Speed	
Cycle	
Number Of Speeds Power Transfer	
Bearings	
	Cholded and Edshedded
Main Specifications:	
Fence Information	
Fence Length	
Fence Width	
Fence Height	5-3/8 in.
Fence Stops	45 and 90 deg.
Cutting Capacities	
Bevel Jointing	90-45 dea.
Maximum Width of Cut	3
Maximum Depth of Cut	
Maximum Rabbiting Depth	3/4 in.
Number of Cuts Per Minute	19800


Cutterhead Information

Features:


Parallelogram Beds
Top Mount Switch Controls
5 3/8" Tall Fence
Included Push Blocks
5" Dust Port

Spiral Cutterhead with German-Made Indexable Carbide Inserts

G0609X 220V Wiring Diagram



Jointer Breakdown



Jointer Breakdown Parts List


NEF	PARI#	DESCRIPTION
1.	D000001	OUTTEDLIE AD O

REF	PART #	DESCRIPTION
1	P0609001	CUTTERHEAD GUARD
4	PFH23M	FLAT HD SCR M8-1.25 X 16
5	P0609005	SPECIAL FLAT WASHER
6	PSS04M	SET SCREW M6-1 X 12
7	P0609007	ADAPTER
8	P0609008	TORSION SPRING
9	P0609009	SHAFT COLLAR
10	PSS04M	SET SCREW M6-1 X 12
11	P0609011	SHAFT
12	P0609012	CUTTERHEAD SCREW
13	PLW06M	LOCK WASHER 10MM
14	PW04M	FLAT WASHER 10MM
15	PK111	KEY 8 X 8 X 60
16	P0609016	CUTTERHEAD PULLEY
17	PVA53	V-BELT A-53 4L530
18	PSB02M	CAP SCREW M6-1 X 20
19	P0609019	BEARING COVER
20	P6206	BALL BEARING 6206ZZ
21	P0609021	BEARING SUPPORT
22	P0452Z001	DRIVER BIT TORX T20
23	P0609X023	SPIRAL CUTTERHEAD 12"
24	P0452Z002	INDEXABLE INSERT 14 x 14 x 2
25	P0452Z009	L-WRENCH TORX T20
26	PFH35M	FLAT HD TORX SCR T20 M6-1 X 15
27	P0609027	BEARING SUPPORT
28	P62042RZ	BALL BEARING 62042RZ
29	PW01M	FLAT WASHER 8MM
30	P0609030	CUTTERHEAD SCREW
31	PN02M	HEX NUT M10-1.5
32	P0609032	BEARING COVER
33	PSB02M	CAP SCREW M6-1 X 20
34	PB156	HEX BOLT M10-1.5 X 150
35	PSS71M	SET SCREW M10-1.5 X 60
36	P0609036	BASE
37	PSS04M	SET SCREW M6-1 X 12
38	PW04M	FLAT WASHER 10MM
39	P0609039	LOCK HANDLE
40	PSS03M	SET SCREW M6-1 X 8
41	P0609041	ECCENTRIC BUSHING
42	P0609042	SHAFT
42-1	P0609042-1	LEFT TORSION SPRING
42-2	P0609042-2	RIGHT TORSION SPRING
43	P0609043	STOP BLOCK
44	PR21M	INT RETAINING RING 35MM

REF PART# **DESCRIPTION**

		5200 1111 11011
45	P0609045	SHAFT
46	PLW06M	LOCK WASHER 10MM
47	PB32M	HEX BOLT M10-1.5 X 25
48	P0609048	BUSHING
49	P0609049	WORM GEAR
50	PK12M	KEY 5 X 5 X 30
51	P0609051	GEAR
52	P0609052	WORM
53	PK37M	KEY 4 X 4 X 16
54	P0609054	SLIDE STOP BLOCK
55	P0609055	SLIDE STOP BLOCK
55-1	PSS16M	SET SCREW M8-1.25 X 10
56	P0609056	SPECIAL FLAT SCREW
57	P0609057	POINTER
58	PW02M	FLAT WASHER 5MM
59	PS09M	PHLP HD SCR M58 X 10
60	PB73M	HEX BOLT M10-1.5 X 50
61	P0609061	CLAMP BLOCK
62	PLW06M	LOCK WASHER 10MM
63	PW04M	FLAT WASHER 10MM
64	P0609064	CLAMPING BLOCK
65	P0609065	CLAMP PLATE
66	PHTEK4M	TAP SCREW M4 X 8
67	P0609067	STOP BUTTON
68	P0609068	START BUTTON
69	P0609069	SWITCH BOX
70	PFS14M	FLANGE SCREW M8-1.25 X 16
71	P0609071	SWITCH BOX BRACKET
72	PB32M	HEX BOLT M10-1.5 X 25
73	PLW06M	LOCK WASHER 10MM
74	PW04M	FLAT WASHER 10MM
75	P0609075	BUTTON PLATE
76	P0609076	BALL STRAIN RELIEF
77	PAW10M	HEX WRENCH 10MM
78	PAW08M	HEX WRENCH 8MM
79	PAW03M	HEX WRENCH 3MM
80	PWR1719	WRENCH 17 X 19
81	PWR1214	COMBO WRENCH 12/14MM
82	PWR1012	COMBO WRENCH 10/12MM
84	P0609084	BUSHING
85	P6202	BALL BEARING 6202ZZ
86	PB06M	HEX BOLT M8-1.25 X 12
87	PW03M	FLAT WASHER 6MM
88	PB02M	HEX BOLT M6-1 X 12

Tables Breakdown




REF	PART #	DESCRIPTION
101	P0609101	TABLE (LEFT)

101	P0609101	TABLE (LEFT)
102	P0609102	TABLE LIP (LEFT)
103	PLW06M	LOCK WASHER 10MM
104	PSB84M	CAP SCREW M10-1.5 X 35
105	P0609105	SHAFT
106	P0609106	TABLE (RIGHT)
107	P0609107	TABLE LIP (RIGHT)
108	PSB84M	CAP SCREW M10-1.5 X 35
109	PLW06M	LOCK WASHER 10MM
110	P0609110	RABBETING ARM

REF PART# **DESCRIPTION**

111	PSB72M	CAP SCREW M10-1.5 X 30
112	PLW06M	LOCK WASHER 10MM
113	P0609113	DEPTH SCALE
114	P0609114	RIVET 2 X 4
115	PW03M	FLAT WASHER 6MM
116	PSB04M	CAP SCREW M6-1 X 10
117	P0609117	DUST DEFLECTOR
118	PSB38M	CAP SCREW M58 X 25
119	P0609119	STOP BLOCK
120	P0609120	BAR

Fence Breakdown




REF PART# DE	SCRIPTION
--------------	-----------

201	P0609201	FENCE BRACKET
202	PW06M	FLAT WASHER 12MM
203	PLW05M	LOCK WASHER 12MM
204	PSB77M	CAP SCREW M12-1.75 X 30
205	P0609205	SLIDING RAIL
206	PSB20M	CAP SCREW M58 X 14
207	P0609207	SLIDING BRACKET
210	P0609210	BLOCK
211	PW01M	FLAT WASHER 8MM
212	PB07M	HEX BOLT M8-1.25 X 25
213	P0609213	COLLAR
214	PSS14M	SET SCREW M8-1.25 X 12
215	PSS04M	SET SCREW M6-1 X 12
216	PB30M	HEX BOLT M8-1.25 X 55
217	PN03M	HEX NUT M8-1.25
218	P0609218	COLLAR
219	P0609219	ECCENTRIC SHAFT
220	P0609220	HANDLE ROD
221	P0609221	HANDLE
222	P0609222	SLIDING BUSHING ASSY
223	PW06M	FLAT WASHER 12MM

REF PART # DESCRIPTION

224	P0609224	SPECIAL HEX NUT M12
225	P0609225	LEFT BRACKET
226	P0609226	PIN
227	P0609227	HANDLE
228	P0609228	HANDLE ROD
229	PN09M	HEX NUT M12-1.75
230	P0609230	FENCE
231	P0609231	CLAMP
232	PSB64M	CAP SCREW M10-1.5 X 25
233	P0609233	LOCK LEVER ASSY
234	P0609234	SPECIAL FLAT WASHER
235	P0609235	DOUBLE END THREADED ROD
236	PRP03M	ROLL PIN 5 X 20
237	P0609237	SPECIAL NUT M12
238	P0609238	SUPPORT BRACKET
239	PB09M	HEX BOLT M8-1.25 x 20
240	PN03M	HEX NUT M8-1.25
241	P0609241	RIGHT BRACKET
242	PN03M	HEX NUT M8-1.25
243	PB20M	HEX BOLT M8-1.25 X 35
245	P0609245	RIVET 2 X 5

Stand Breakdown




Stand Parts List

REF	PART#	DESCRIPTION
301	P0609301	LEFT ACCESS DOOR
301-1	PSBS18M	BUTTON HD CAP SCR M6-1 X 18
301-2	PW03M	FLAT WASHER 6MM
302	P0609302	DUST HOOD
302-1	PSBS11M	BUTTON HD CAP SCR M6-1 X 10
304	PHTEK4M	TAP SCREW M4 X 8
305	P0609305	CABINET
306	P0609306	RUBBER WASHER 8MM
307	PSS80M	SET SCREW M8-1.25 X 15
308	P0609308	PULLEY COVER
309	P0609309	TENSION ROD
310	PW06M	FLAT WASHER 12MM
311	PN09M	HEX NUT M12-1.75
312	P0609312	TENSION PLATE
313	PB116M	HEX BOLT M10-1.5 X 45
314	PW04M	FLAT WASHER 10MM
315V2	P0609X315V2	MOTOR 3HP 220V V2.05.08
315-1V2	PK33M	KEY 5 X 5 X 45
315-2V2	P0609X315-2V2	FAN COVER V2.05.08
315-3V2	P0609X315-3V2	MOTOR FAN V2.05.08
315-4V2	P0609X315-4V2	CENTRIFUGAL SWITCH V2.05.08
315-5V2	P0609X315-5V2	S CAPACITOR 250M 250V 1-3/4 X 3-1/2
315-6V2	P0609X315-6V2	R CAPACITOR 40M 450V 1-3/8 X 2-3/8
315-7V2	P0609315-7V2	JUNCTION BOX V2.05.08
316	P0609316	MOTOR PULLEY
317	PSS75M	SET SCREW M10-1.5 X 16
318	P0609318	MOTOR BRACKET
319	PN09M	HEX NUT M12-1.75
320	PN02M	HEX NUT M10-1.5
321	P0609321	PULLEY COVER LOCK KNOB
322	PSBS18M	BUTTON HD CAP SCR M6-1 X 18
323	P0609323	RIGHT ACCESS DOOR
324	P0609324	SPECIAL HEX NUT M6

REF	PART #	DESCRIPTION
325	PW03M	FLAT WASHER 6MM
326	P0609326	ADAPTER
327	P0609327	LATCH
328	P0609328	SMALL STRAIN RELIEF
329	PSB64M	CAP SCREW M10-1.5 X 25
330	PLW06M	LOCK WASHER 10MM
331	P0609331	BIG STRAIN RELIEF
332	PSB04M	CAP SCREW M6-1 X 10
333	PW03M	FLAT WASHER 6MM
334	P0609334	MAGNETIC SWITCH
334-1	PS06M	PHLP HD SCR M58 x 20
334-2	P0609334-2	CONTACTOR
334-3	P0609334-3	MAG SWITCH FRONT COVER
334-4	P0609334-4	THERMAL OVERLOAD RELAY
334-5	P0609334-5	MAG SWITCH BACK COVER
335	P0609335	SWITCH PLATE
336	PW02M	FLAT WASHER 5MM
337	PN06M	HEX NUT M58
338	PSS03M	SET SCREW M6-1 X 8
339	P0609339	COLLAR
340	P0609340	SPIRAL GEAR SHAFT
341	PR29M	INT RETAINING RING 32MM
342	P6201	BALL BEARING 6201ZZ
343	P0609343	BEARING SUPPORT
344	PFH04M	FLAT HD SCR M6-1 X 8
345	PFS14M	FLANGE SCREW M6-1 X 16
346	P0609346	HANDWHEEL
347	PRP78M	ROLL PIN 4 X 10
348	PN09M	HEX NUT M12-1.75
349	PW06M	FLAT WASHER 12MM
350	P0609350	FOLDING HANDLE
351	PK34M	KEY 5 X 5 X 20
352	P0609352	PUSH BLOCK

Labels Breakdown



DEE	PART #	DESCRIPTION
KEF	PARI#	DESCRIPTION

401	P0609X401	MACHINE ID LABEL
402	P0609402	CUTTERHEAD WARNING LABEL
403	P0609403	CUTTERHEAD GUARD LABEL
404	PLABEL-14	ELECTRICITY LABEL
405	P0609405	CONTROL PANEL FACE
406	PLABEL-11	SAFETY GLASSES LABEL
407	PLARFI -12A	READ MANUAL LABEL

DEE	PART #	DESCRIPTION
KEF	PARI#	DESCRIPTION

408	PLABEL-15	EAR PROTECTION LABEL
409	G8589	GRIZZLY NAME PLATE-LARGE
410	P0609X410	MODEL NUMBER LABEL
411	P0609411	RESPIRATOR-HEARING LABEL
412	PLABEL-02B	UNPLUG POWER 220-440 LABEL
413	PPAINT-1	GRIZZLY GREEN PAINT
414	PPAINT-11	PUTTY TOUCH UP PAINT

AWARNING

Safety labels warn about machine hazards and ways to prevent injury. The owner of this machine MUST maintain the original location and readability of the labels on the machine. If any label is removed or becomes unreadable, REPLACE that label before using the machine again. Contact Grizzly at (800) 523-4777 or www.grizzly.com to order new labels.

G0609X ACCESSORIES

G3640—Power Twist® V-Belt - 1/2" x 48"

Smooth running with less vibration and noise than solid belts. The Power Twist® V-belt can be customized in minutes to any size—just add or remove sections to fit your needs. Size: ½" x 48"; replaces all "A" sized V-belts. Requires two Power Twist® V-belts to replace the stock V-belt on the Model G0609X.




Figure 2. G3640 Power Twist® V-Belt.

H9291—12" Byrd® Shelix Cutterhead

Made in the USA by Byrd, this indexable carbide insert cutterhead is the best money can buy—period! The inserts are not only placed in a spiral pattern, they are also positioned at an angle so the shearing action leaves a glassy smooth cut on the toughest and most figured woods. Comes with 5 extra replacement inserts. Very nice upgrade!




Figure 3. Byrd Shelix Cutterhead.

H7319—10 pk. of Carbide Inserts 14x14x2mm

H1411—PowerHands™ Safety Stick

This safety push stick features interchangeable traction treads; one for flat stock, and one for pressing against table and fence. It also has a spring loaded push-pin for full workpiece contact. Made in the USA.



Figure 4. H1411 PowerHands™ Safety Stick.

G5562—SLIPIT® 1 Qt. Gel G5563—SLIPIT® 12 oz Spray G2871—Boeshield® T-9 12 oz Spray G2870—Boeshield® T-9 4 oz Spray H3788—G96® Gun Treatment 12 oz Spray H3789—G96® Gun Treatment 4.5 oz Spray



Figure 5. Recommended products for protecting unpainted cast iron/steel parts on machinery.